


WIRING SCHEMATIC FOR 831K.1.1AC



| No | QTY. | PART No. | DESCRIPTION |
|----|------|------------|--------------------------|
| 1 | 1 | 83-49-1 | 2 Button Remote |
| 2 | 2 | 81-13-6 | Modular Connector-6 Pole |
| 3 | 2 | 85-38-7 | SPL Control Board |
| 4 | 2 | 81-94-3 | 4" Jumper Wire |
| 5 | 1 | 25-128-1 | Power Supply Cord |
| 6 | 1 | 81-50-2 | Ring Connector #8 |
| 7 | 1 | 80-70 | Transformer |
| 8 | 2 | 80-59-60CE | Gear Motor |

